

CLASSIFIED MESSAGE

25X1

25X1

ORIG :
INT :
EXT :
DATE :
TO :
FROM :
CONF :
INFO :

Approved For Release 2005/02/10 : CIA-RDP75B00159R000100170044-5
ANS/OSA
2 JANUARY 1969

SECRET

3 JAN 69 13 47 Z

EO/SA

DD/SA

D/SA

Last Del. Fail - 3 Jan

ROUTING									
1	EB/OSA								
2	D/H/OSA								
3	D/E/OSA								
4	D/SA								
5	D/R&D/OSA								
6	D/O/OSA								
7	ISRA/OSA								
8	CHD/OSA								
<table border="1"> <tr> <td>DEFERRED</td> <td><input checked="" type="checkbox"/></td> <td>PRIORITY</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>ROUTINE</td> <td><input type="checkbox"/></td> <td>OPERATIONAL IMMEDIATE</td> <td><input type="checkbox"/></td> </tr> </table>		DEFERRED	<input checked="" type="checkbox"/>	PRIORITY	<input checked="" type="checkbox"/>	ROUTINE	<input type="checkbox"/>	OPERATIONAL IMMEDIATE	<input type="checkbox"/>
DEFERRED	<input checked="" type="checkbox"/>	PRIORITY	<input checked="" type="checkbox"/>						
ROUTINE	<input type="checkbox"/>	OPERATIONAL IMMEDIATE	<input type="checkbox"/>						
861									

TO

INFO

SECRET

CITE

25X1

9058

25X1

IDEALIST/

SUBJECT: LOX CONVERTER CHECK VALVES

25X1

REF: (1) DATED 19 DECEMBER 68
(2) DATED 30 DECEMBER 68
(3) DATED 23 DECEMBER 68

1. DOES NOT CONCUR WITH RECOMMENDATION IN REF 2 TO REPLACE ALL EXISTING CHECK VALVES WITH STAINLESS STEEL VALVE BODIES AT THIS TIME FOR THE FOLLOWING REASONS:

A. MORE FLIGHT EXPERIENCE IS REQUIRED TO VERIFY WHETHER OR NOT THE POPPET REDESIGN AS PER REF 1 HAS SOLVED THE LOX PROBLEMS. THESE CHANGES WERE MADE TO MAKE THE VALVE LESS SENSITIVE TO CONTAMINATION. IF FLIGHT EXPERIENCE SHOWS CONTINUED LOX PROBLEMS AND EVIDENCE OF ALUMINUM DEPOSITS IS FOUND ON DISASSEMBLY, THEN ALTERNATIVE ACTION MUST BE TAKEN. IN THE MEANTIME, TESTS MUST BE CONDUCTED

COORDINATING OFFICERS

RELEASING OFFICER

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Capt. No.

SECRET

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

ROUTING	DEFERRED	<input checked="" type="checkbox"/>	PRIORITY	INITIALS
	ROUTINE		OPERATIONAL IMMEDIATE	INITIALS

INFO:
INIT:
EXT:
DATE:

TO:

FROM:

CONF:

INFO:

PAGE 2

TO INFO CITE

BY [] TO DETERMINE SUITABILITY OF STAINLESS STEEL VALVE BODIES WITH RESPECT TO ADEQUATE SEALING OF THE POPPETS AGAINST STAINLESS STEEL SEATS PRIOR TO ANY IN FLIGHT USE. LIQUID LEAKAGE COULD RESULT IN HIGH PRESSURE/QUANTITY LOSS PROBLEMS.

B. IF FRETTING OR ELECTROLYTIC ACTION IS A PROBLEM WITH THIS VALVE, IS THE SR-71, THAT HAS IDENTICAL VALVES AND COMPONENTS, EXPERIENCING THIS PROBLEM? IF NOT, WHAT IS UNIQUE ABOUT THE U-2R SYSTEM? ANSWERS TO THESE QUESTIONS MIGHT PROVIDE JUSTIFICATION FOR CHANGING THE VALVE BODY.

C. INVESTIGATIONS OF ALTERNATE SOLUTIONS, BESIDE STAINLESS STEEL VALVE CASES, MUST BE GOING ON WHILE FLIGHT EXPERIENCE WITH REDESIGNED POPPETS IS ACCUMULATING, IN THE EVENT THE LATTER EFFORT FAILS TO SOLVE THE PROBLEMS. INVESTIGATIONS SHOULD INCLUDE THE USE OF FILTERED CHECK VALVES AND THE USE OF LOX SYSTEMS WITHOUT CHECK VALVES SINCE OTHER AIRCRAFT USE BOTH SUCH SYSTEMS.

COORDINATING OFFICERS

SECRET

RELEASING OFFICER

GROUP 1
Excluded from automatic
downgrading and
declassification

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.

ORIG:
UNIT:
EXT:
DATE:

SECRET

ROUTING	
1	2
3	10
4	11
5	12
6	13
7	14
8	15
9	16

PRIORITY	DEFERRED	<input checked="" type="checkbox"/>	PRIORITY	INITIALS
	ROUTINE		OPERATIONAL IMMEDIATE	INITIALS

TO :
FROM:
CONF:
INFO:

PAGE 3

TO INFO CITE

D. REGARDING DIFFICULTY IN CHANGING CHECK VALVES DUE TO
THREAD SEIZURE, THIS PROBLEM CAN BE TEMPORARILY OVERCOME
AS INDICATED IN REF 3. AS AN ALTERNATIVE PERMANENT FIX,
CHANGING THE MATERIAL OF THE MOUNT (P/N: DN-F-7405113-1)
FROM ALUMINUM TO A HARDER MATERIAL (STAINLESS) SHOULD BE
CONSIDERED SINCE THIS ITEM ALSO HAS 3 OTHER TAPPED PORTS
(1 FOR RELIEF VALVE, 2 FOR TUBING FITTINGS), INADDITION
TO THE CHECK VALVE PORT, THAT CAN EXPERIENCE SEIZURE
PROBLEMS DURING MAINTENANCE.


END OF MESSAGE

COORD:

[Signature]
D/H/OSA

[Signature]
D/RED/OSA

25X1




AMS/OSA

COORDINATING OFFICERS

SECRET

RELEASING OFFICER



AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.